

# Mini Bulletin XR21E

Xerox® AltaLink® B8045/B8055/B8065/B8075/B8090  
Xerox® AltaLink® C8030/C8035/C8045/C8055/C8070  
SPAR Release 103.xxx.001.05400 (R21-02)

Bulletin Date: March 4, 2021

Updated: April 22, 2021

## Purpose

This Bulletin is intended ONLY for the specific security issues identified below which have been rated with a criticality level of IMPORTANT.

Includes fixes for the following:

- Authenticated OS command injection (RCE)
- Unauthorized Filesystem Access
- Audit log improvements
- Removed the ability to disable McAfee Embedded Control
- Bug fix to IPSec

## Software Release Details

Please review this bulletin and consider installation of these versions.

Note: If your software is higher or equal to the versions listed below no action is needed.

Model	AltaLink B8045/B8090	AltaLink C8030/C8035	AltaLink C8045/C8055	AltaLink C8070
System SW version	103.008.001.05400	103.001.001.05400	103.002.001.05400	103.003.001.05400
Link to SW BDC* update and Install Instr	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>
Link to SW AltBoot update and Install Instr	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>

Unzip the file to a known location on your workstation/computer.

\*Binary Disk Compression

## Acknowledgement

Xerox would like to thank the Airbus security team for informing us of the need to address the security issue.

Xerox would like to thank Nicolas Heiniger with the Compass Security team for informing us of the need to address the first security issue.

